

Total Removal of lead

When total removal of lead is required, EPA and OSHA dictate the use of very specific procedures (EPA 40 CFR Part 745, section L; OSHA 29 CFR 1910 and 1926). These processes are briefly outlined in Appendix B. It is not anticipated that total removal will be performed by Northern Arizona University employees. Should this become an issue, the Certified Renovator must work with EHS to implement EPA and OSHA compliant procedures.

Additional Details on Lead Safety may be found in the NAU [Lead Safety Manual](#).

Contact and additional program information for NAU EH&S safety personnel and programs is available on the EH&S Website <http://nau.edu/Research/Compliance/Environmental-Health-and-Safety/> or by using the EH&S switchboard email regulatorycompliance@nau.edu or switchboard phone number (928)-523-7288.